1	2
6	0

DART AEROSPACE LTD

Work Order: 2.1007

Description: Saddle Kit

Part Number: K10003

Qty: #55

Page 1 of 1

Step	Location	Procedure	Ву	Date	Qty
1	DC	Issue Traveller	#	14.06.08	18
2	DC	Photocopy bluefile and type labels per PPP K10003 CHG004 F0L D205-634-011 Q D204-635-011 Wk 26 +	-13	r04.06.24	18
3	ST	Pick: Oty Part Number Description Batch 1		20	
4	QC4	29, MS21042L4 Nut (or MS21042-4) M14478 Inspect 100% kit for completeness on the W/O	Cyl	04/07/09	18
5	PK	Pack per PPP K10003 ReJ. F	50	04/08/0	1
6	AC	Cost / part: 474.74	546	04.08.06	5
7	DC	Close W/O 481.55 Inspection Level 21	45	44.08.10	5

Data	Change	Revised By	Approved
	Add to the service and sounding K10003 ray A (ECN 296)	FC	
The second secon	Added revisions per new dwg K 10003 lev. A (Lott 200)		
00.11.09	Added AN960JD1016 and D2707-041 to the pick list		
01 09 24	Removed paper work and labels.		
		- Contract of the Contract of	-
	Added D2968-041 tow ring Change 002		
	Reformat: Incorporated D205-641-011	KJ/RF	
	Date 00.06.26 00.11.09 01.09.24 01.11.29 02.04.11 03.01.16	00.06.26 Added revisions per new dwg K10003 rev.A (ECN 296) 00.11.09 Added AN960JD1016 and D2707-041 to the pick list 01.09.24 Removed paper work and labels. 01.11.29 Added paper work and labels 02.04.11 Added D2968-041 tow ring Change 002	Date Change 00.06.26 Added revisions per new dwg K10003 rev.A (ECN 296) EC 00.11.09 Added AN960JD1016 and D2707-041 to the pick list EC 01.09.24 Removed paper work and labels. SM 01.11.29 Added paper work and labels SM 02.04.11 Added D2968-041 tow ring Change 002 NG



RF 05.27

		fell	